Work	Order	ID	54530
VVOIE	vraer	117	34330



Page 1

December 10, 2009 3:46:56 PM

Item I	D:
--------	----

D3049-1

Bearpaw

Accept



Setup Start

Stop

Revision ID:

Item Name: Start Date:

10/12/2009

Start City: 8.00 Rea'a Otv: 8.00

Cust Item ID:

Customer:

Draw

Number

Reference:

Approvals:

Process Plan:

Date JAJ

Tooling:

Date:

Run

Start

Required Date: 18/12/2009

Date:

SPC (Y/N):

Date:

Stop

Sequence ID/ Work Center ID Operation Description Set Up/ **Run Hours**

Rev.

Plan Draw Code

Accept Qty Qty

Reject Reject Number

Insp. Stamp

Draw Nbr

Rev A1

Revision Nbr

D3049 120

HAAS 1

HAAS CNC vertical machine #1

HAAS CNC VERTICAL MACHINING #1

Memo

0.00

0.00

1-Inspect material for defects or damage prior to machining

2-Machine as per Folio FA165 and Dwg D3049Identify as D3049-1

3-Deburr

130

QC2- Inspect parts off machine FAI/FAIB

0.00

Quality Control

Memo

0.00

140

QC8- Inspect parts - second check

0.00

H.A 09/12/21

U Quality Control

Memo

0.00

平 9-12-16

Da	ari	tΑ	erc	sp	ac	e L	.td
----	-----	----	-----	----	----	-----	-----

		. —							
W/O:			WO	RK ORDER CHANG	ES				
DATE	STEP	PRO	OCEDURE CHAN	IGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			•		•				
Part No	:	PAR #:	Fault Categ	ory:	_ NCR: Yes	No DQ	A:	Date:	
	R	esolution:	Disposition	:	_ QA: N/C C	losed:		Date: _	
NCR:			WORK ORDE	R NON-CONFORMA	NCE (NC	R)			
DATE	STEP	Description of NC		Corrective Action Secti		Verifi	cation	Approval	Approval
DAIL	SIEF	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Date	& Sect	ion C	Chief Eng	QC Inspector
4				*					

Work Order ID 54530

Page 2

December 10, 2009 3:46:56 PM

Required Date: 18/12/2009

Item ID: **Revision ID:** D3049-1

Bearpaw

Accept



Setup Start

Stop



Item Name: **Start Date:**

10/12/2009

Start Qty: 8.00 Req'd Qty: 8.00

Cust Item ID:

Customer:

Draw

Number

Reference:

A	nn		va'	le.	
А	un	ro	VИ	18:	

Process Plan:

Operation

Packaging

Date:

Tooling:

Date:

Run Start

Reject

Qty

Accept

Qty



QC:

Date:

SPC (Y/N):

Set Up/

Run Hours

Date:

Draw

Rev.

Plån

Code

Stop



Insp.

Stamp

Sequence ID/ Work Center ID

170

Description

Identify as per dwg & Stock Location:

0.00

Packaging

Packaging

Memo

0.00

180

QC

Quality Control

QC21- Final Inspection - Work Order Release

0.00

Memo

0.00

Reject

Number

C209112121

Dart Aerospace Ltd	erospace Ltd
--------------------	--------------

Dail Aci	Copacc								
W/O:			W	ORK ORDER CHANGE	ES			· · · · · · · · · · · · · · · · · · ·	
DATE	STEP	PRC	CEDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
									·
Part No	:	PAR #:	Fault Cat	egory:	NCR: Yes	No DQA	۸:	_ Date: _	
		esolution:							
NCR:		\	WORK OR	DER NON-CONFORMA	NCE (NCR)			
DATE	STEP	Description of NC		Corrective Action Section		Verific	ation	Approval	Approval
DATE	SIEF	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section	on C	Chief Eng	QC Inspector
				·				:	
		. ,							
						-			

Picklist Print

December 10, 2009 3:47:00 PM

Work Order ID: 54530

Parent Item:

Comments:

100

D3049-1

Parent Item Name: Bearpaw



Start Date: 10/12/2009

Required Date: 18/12/2009

Start Qty: 8.00

Required Qty: 8.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Ten Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	R≸maining Qty To Pick	Qty Issued	Date Issued	Status
MUHMWB10		Purchased	No	· · · · · · · · · · · · · · · · · · ·		120	sf	383.3041	27.2000			
											OR 9-12-16	5

UHMW I" Black

Warehouse	Loc Oty	Loc Code	i
Location			
Main Warehouse			İ
MAT	341.2164		<u> </u>
112186	122.0164		<u> </u>
112514	11.2] _
113166	208		
Main Warehouse			ļ
ST	42.0877		_
111354	42.0877		_

113166

Dart Aerospace Ltd	Dart	Aeros	pace	Ltd
--------------------	------	-------	------	-----

		— - - ·								
W/O:			V	ORK ORDER CHANGE	ES					<u> </u>
DATE	STEP	PRO	CEDURE CH	IANGE	*	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
						·				
			· · · · · · · · · · · · · · · · · · ·		,					
Part No	:	PAR #:	Fault Ca	tegory:	NCI	R: Yes	No DQ	A:	Date: _	
,	Re	esolution:	_ Disposit	ion:	_ QA	N/C CIG	sed:		Date: _	
NCR:		V	ORK OR	DER NON-CONFORMA	NCE	(NCR)			
DATE	STEP	Description of NC		Corrective Action Section	on B		Verifi	cation	Approval	Approval
DATE	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Sect	ion C	Chief Eng	QC Inspector
					•					
				*						

				,						
										,

DART AEROSPACE LTD	Work Order:	54530
Description: Bearpaw	Part Number:	D3049-1
Inspection Dwg: D3049 Rev: A1		Page 1 of 1

FIRST ARTICLE INSPECTION CHECKLIST

X First Article	Prototype
-----------------	-----------

Inspection Sheet Drawing Dimension					Reject	Method of Inspection	Comments
Α	Ø0.260	+0.005/-0.000	0,260				
В	0.93	+/-0.030	0.923				
С	0.40	+0.030/-0.000	0,405	$\sqrt{}$			
D	2.00	+/-0.030	2.00	√,			
Е	10.250	+/-0.010	10,250			,	
F	4.540 🦡	+/-0.030	4.540	$\sqrt{}$			
G	5.88	+/-0.030	5.88	√			
Н	0.38	+/-0.030	38	~/			
ı	11.50	+/-0.030	11.50	<u> </u>			
J	0.07 x 45°	+0.030/-0.010	.07×45°	J			
К	0.44 - 0.47	+/-0.000	60/4.	7			
L	R0.25	+/-0.030	8.35	V			
М	0.38	+/-0.010	.376	V			
N	0.95	+0.030/-0.010	980	J			
0	0.69	+/-0.030	Pi	✓			
Р	0.20	+/-0.030	<i>E</i> 6	<u> </u>			
Q	23.00	+/-0.030	33.00	V			
R	0.25 x 45°	+/-0.030	92×1120	<u> </u>			
				-			

Measured by:F	Audited by: 8.A	Prototype Approval:	N/A
Date: 0/12/19	Date: 09 12 21	Date:	N/A

ı	Rev	Date	Change	Revised by	Approved
	A	03.09.22	New Issue P/O D135-692-011	KJ/RF	
	В	08.05.06	Dimension I revised	KJ/DD 👭	

	•				
_		A		1	4 -1
	211	ΜΩΓΩ	vena	CO 1	TO
u	aıı	Aero	JJUG	CCL	···


<u> </u>										
W/O:			V	ORK ORDER CHANG	ES					. \$68, 1
DATE	STEP	PROC	PROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		•								
									•	
		,								
Part No	•	PAR #:	Fault Ca	tegory:	NC	R: Yes I	No DQ	\ :	Date:	
Resolution:										
NCR:		W	ORK OR	DER NON-CONFORM		(NCR)			//
DATE	STEP	Description of NC	Corrective Action Section			verific			cation Approval	Approval
	0.2.	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Secti	on C 	Chief Eng	QC Inspector
							•			
		,								
									·	
		·		ŗ.						٠.
· <u> </u>										
				,						
	1						1		1	1





	DESIG	ŘF	DRAWN BY	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
1	CHECK	(ED,	APPROVED	DRAWING NO.	REV. A
1	•	#	1 #	D3049 SHEET	1 OF 2
	DATE	·····	1	TITLE	SCALE
	01 1	0.18		BEARPAW	1:7
	Α		/ 01.10.18	NEW ISSUE	
	ΑI	#	₹ 03.01.13	\$0.73 WAS \$0.75	

RELEASED



D3049-1 BEARPAW

RETURN TO ENGINEERING

UNCONTROLLED COPY

SUBJECT TO AMENDMENT

WITHOUT NOTICE

WORK ORDER

NOTES:

1) BEARPAW IS SYMMETRIC ABOUT CENTER LINE

2) MATERIAL: UHMW BLACK PER SPEC CONTROL DRAWING D2689,

1.00" THICK (MACHINE TO 0.950)

Copyright @ 2001 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.


Dart	Aer	ospa	ce	Ltd
------	-----	------	----	-----


W/O:			W	ORK ORDER CHANG	GES				
DATE	STEP	PR	OCEDURE CH	ANGE	Ву	Da	te Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
				, , , , , , , , , , , , , , , , , , , ,		· .			
				, , , , , , , , , , , , , , , , , , ,					
Part No		PAR #:							
	R	esolution:					d:	Date: _	
NCR:		,	WORK ORI	DER NON-CONFORM	ANCE (N	CR)			*
DATE	STEP	Description of NC	Description of NC Section A			ın &	/erification	Approval	Approval
		Section A	Chief Eng	Chief Eng		ate	Section C	Chief Eng	QC Inspector
					ļ				
		·							
				:					
				. Access to service and the first					
			*,						


11/054530



			1/1//
DESIGN RF	DRAWN BY	DART AER	ROSPACE LTD , ONTARIO, CANADA
CHECKED,	APPROVED	DRAWING NO.	REV. A
#	H	D3049	SHEET 2 OF 2
DATE		TITLE	SCALE
01.10.18		BEARPAW	1:6







Copyright © 2001 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

Dail Ac	Ospace	, Ltu								
W/O:			WORK ORDER CHANGES							
DATE	STEP		PROCEDURE CHANGE				Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
					·					
Part No	•		PAR #:	Fault Category:		NCR: Yes	No DQ	A:	Date:	
	R	esolution:		Disposition:		QA: N/C C	losed:		Date: _	

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification	Approval	Approval
			Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector
							·	
				•		i		
				2				
_						-		
						•		